KEARNY MARSH RESTORATION
LAB ANALYSIS SUBMISSION

Doc ID: <u>32</u>

Data Submitted by: <u>Steve Yergeau</u>   Date: January 2, 2007

Data Collected by: Steve Yergeau, Mike Wallendjack, Matt Oleske

Data Analyzed by: Steve Wall, Derek Wright

Project PI: Dr. Lisa Totten

Analysis is one of the following (please **bold** if submitting electronically, *circle* if submitting in paper form)**:**

      Soil/Sediment (bulk soil, dry soil, or porewater)
      Surface Water (dissolved, particulate, or whole water)
      Groundwater (dissolved, particulate, or whole water)
      Air (gas, particle, precipitation)
      Detritus
      Biota (specify)
      Other

Short Description of Data Collection:

Date Collected: June 30 & July 5, 2006

Groundwater samples were collected from the 12 monitoring wells installed around the perimeter of Kearny Marsh (Grid 7, Grid 15, Grid 13, Grid 39 and Grid 42).

Method Detection Limit Information:

Please use this area below to describe MDLs appropriate for this analysis. Please include the units.

Analysis	MDL
Pd	
Ag	
Cd	
Sb	
Pb	
V	
Cr	
Fe	
Co	
Ni	
Cu	
As	
Zn	
Mn	
Hg	
PCBs	
PAHs	

Contact Information: Dr. Lisa Totten: totten@envsci.rutgers.edu